

In this Issue:

Unicorn Board Enclosure2

Technical Bulletin Distribution:

The Lancer Engineering Department publishes a Technical Bulletin every other month. To subscribe or unsubscribe from the Tech Bulletin, go to lancerworldwide.com. Lancer Installation and Service Manuals, Instruction Sheets, previous Technical Bulletins, and a complete index of Technical Bulletin articles are also available at lancerworldwide.com. For general questions about the Tech Bulletin, email custserv@lancerworldwide or call (888) 846-6729.

Contact Information:

Lancer Sales: (800) 729-1500
Lancer Customer Service: (800) 729-1500
Lancer Warranty: (800) 729-1550
Lancer USA: (210) 310-7000
Canada: (210) 310-7187
Latin America: (210) 310-7000
International Sales: (210) 310-7063
Europe: 32-2-755-2390
Australia/New Zealand: 61-8-8268-1388
Email: custserv@lancerworldwide.com
Lancer Website: www.lancerworldwide.com



Issue:

Unicorn Tower printed circuit board (PCB) shorting out due to splashing.

Cause:

Splashing is often seen in these applications for various reasons like mishandled drinks, loose connections, etc.


Correction:

Concerned with the potential of splashing, Lancer has taken this feedback as an opportunity to enhance the design.

While not intended to be a watertight seal, the redesigned enclosure provides an effective method to deflect splashed liquid, thereby protecting the components and performance of the PCB.



Splash Proof Enclosure



Order kit PN: 82-7107 to upgrade your tower.



Instruction sheet (PN: 28-3142) included in kit.